



FIRST AID
FOR
WELLS



MADE IN
USA

12-1 lb. containers
Item# 24-905

Before Drilling a New Well, Rejuvenate it with **RenuWell**

The #1 reason for well failure is mineral deposits clogging the well points

RenuWell

- ◆ Dissolves mineral build-up from well points
- ◆ Non-corrosive to system
- ◆ Inhibited against corrosion to metals
- ◆ Clear Flow Indicator identifies when system is ready to use again
- ◆ Use on drive points 1 1/4" to 4" in diameter and with 3 to 5 feet of screen

Just apply and let stand for 24 hours. Then flush until Clear Flow Indicator dye disappears and water runs clear. *No guessing!*



Don't Replace your Well, Restore it with **RenuWell**

UTILITY

700 MAIN STREET, WESTBURY, NY 11590 U.S.A.
(516) 997-6300 • FAX# (516) 997-6345 • www.UtilityChemicals.com